Westhertzenon Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-0956/1

Work Order Type: Weatherization

Audit Name: 17017UC-0956

CLIENT INFORMATION

Client ID: 17017UC-0956

AGENCY INFORMATION

Agency: Upper Cumberland H R A Agency Phone: (931) 528-1127

Address: 3313 Williams Enterprise Drive Fax:

Cookeville, TN 38506 *Email Address:*

Agency Contact: Asberry, Kevin Work Phone:
Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

1956 site built home 880 sq. ft

	Measure 1	W/L	ID SLAB WOOD PRE-H OCKSET DBL WINDOV RIOR TRIM		OR	Componen	its			Inspected
C	omment									
						Estimated	<u> </u>		Actual	
#	Material / Lak	oor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified		Misc Material	Each	1					
C	Other Detail				1] [1		
L										
]		
					Measu	re Sub Total:			Sub Total:	
C	for we	indation	cess door w. weatherstrip on access door strip door using silicone l reshold		herstrip)				
						Estimated			Actual	
	Material / Lat		Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Miscellaneou Supplies	IS	Infiltration Reduction	Each	1					
C	Other Detail									
					Measu	e Sub Total:			Sub Total:	
	Field Notes:									

Measure 3 DWI	H Pipe Insulation			Componen	its			Inspected
Comment				Estimated	ı		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
	wrap water pipes							
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail						1		
			Measur	e Sub Total:			Sub Total:	
Measure 4 Floo Comment	or Ins. R-19			Componen			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	880					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

1 Hot Water Equipment R-10 minimum-use bubble wrap 2 Labor DHW Tank Insulation Each 1 Other Detail Measure Sub Total: Sub Total: Field Notes: Measure 6 Attic Ins. R-30 Comment Estimated Actual		H Tank Insulation			Componen	ts			Inspecte
# Material / Labor Description / Comment Units Qty Unit Cost Total Qty Unit Cost Total Hot Water Equipment Property Property	Comment								
1 Hot Water Equipment R-10 minimum-use bubble wrap 2 Labor DHW Tank Insulation Each 1 Other Detail Measure Sub Total: Sub Total: Field Notes: Measure 6 Attic Ins. R-30 Components Estimated Actual Material / Labor Description / Comment Units Qty Unit Cost Total Qty Unit Cost T I Insulation Attic Insulation - Blown Cellulose - R-30					Estimated	<u>'</u>		Actual	
R-10 minimum-use bubble wrap 2 Labor DHW Tank Insulation Each 1	# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
bubble wrap 2 Labor DHW Tank Insulation Each 1		DHW Tank Insulation	Each	1					
Other Detail Measure Sub Total: Sub Total: Field Notes: Measure 6 Attic Ins. R-30 Components A1 Estimated Actual Material / Labor Description / Comment Insulation Attic Insulation - Blown Cellulose - R-30 Actual Sub Total: Sub Total:									
Measure Sub Total: Sub Total: Field Notes: Measure 6 Attic Ins. R-30 Components A1 Estimated Actual Material / Labor Description / Comment Insulation Attic Insulation - Blown Cellulose - R-30 Measure Sub Total: Sub Total: Insulation Attic Ins. R-30 Components A1 Loss Actual Actual Actual Qty Unit Cost Total Qty Unit Cost Total Collulose - R-30	2 Labor	DHW Tank Insulation	Each	1					
Field Notes: Measure 6 Attic Ins. R-30 Components A1 Inspection	Other Detail						1		
Field Notes: Measure 6 Attic Ins. R-30 Components A1 Inspection									
Field Notes: Measure 6 Attic Ins. R-30 Components A1 Estimated Actual # Material / Labor Description / Comment Units Qty Unit Cost Total Qty Unit Cost T I Insulation Attic Insulation - Blown Cellulose - R-30									
Measure 6 Attic Ins. R-30 Components A1 Estimated Actual Material / Labor Description / Comment Units Qty Unit Cost Total Qty Unit Cost Total Insulation Attic Insulation - Blown Cellulose - R-30							7		
# Material / Labor Description / Comment Units Qty Unit Cost Total Qty Unit Cost Total 1 Insulation Attic Insulation - Blown Cellulose - R-30	Field Notes:			Measur	e Sub Total:		,	Sub Total:	
1 Insulation Attic Insulation - Blown SqFt 880 Cellulose - R-30	Measure 6 Atti	ic Ins. R-30		Measur	L	ts A1		L	Inspecte
Cellulose - R-30	Measure 6 Atti	ic Ins. R-30		Measur	Componen				Inspecte
Other Detail	Measure 6 Atti Comment				Componen Estimated	<u> </u>		Actual	Inspecte Total
	Measure 6 Atti Comment # Material / Labor	Description / Comment Attic Insulation - Blown	Units	Qty	Componen Estimated	<u> </u>		Actual	
	Measure 6 Atti Comment # Material / Labor 1 Insulation	Description / Comment Attic Insulation - Blown	Units	Qty	Componen Estimated	<u> </u>		Actual	
	Measure 6 Atti Comment # Material / Labor 1 Insulation	Description / Comment Attic Insulation - Blown	Units	Qty	Componen Estimated	<u> </u>		Actual	
Measure Sub Total: Sub Total:	Measure 6 Atti Comment # Material / Labor 1 Insulation	Description / Comment Attic Insulation - Blown	Units	Qty	Componen Estimated	<u> </u>		Actual	
Field Notes:	Measure 6 Atti Comment # Material / Labor 1 Insulation	Description / Comment Attic Insulation - Blown	Units SqFt	Qty 880	Componen Estimated Unit Cost	<u> </u>	Qty	Actual Unit Cost	

Measure 7 Stor	m Windows			Componen	<i>ts</i> A6,A2			Inspecte
Comment				Estimated	,		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
3 Other	Storm Window	Each Window	4					
	<99 U.I ea Over 100 UI							
Other Detail						1		
			Measur	e Sub Total:			Sub Total:	
Measure 8 CO I Comment	Monitor is Needed			Componen Estimated			Actual	Inspecte
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	9-volt CO Monitor	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:						-		

	<i>Measure</i> 9 Smo	ke Detector is Needed			Componen	ts		I	nspected
C	Comment								
				Estimated				Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	9-volt Smoke Detector	Each	1					
2	Labor	Labor	Hour	1					
(Other Detail						1		
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								
l									
			Work Or	der Gra	nd Total:		Gran	d Total:	